PRELIMINARY SUMMARY OF MAP ACTIONS

Community: EXETER, TOWN OF Community No: 330130

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	02-01-1294A	07/19/2002	ASSESSOR'S MAP 62, LOT 64--13 MILLSTREAM DRIVE	3301300003B	33015C0401F
LOMA	06-01-0162A	01/12/2006	11 MILLSTREAM DRIVE	33015C0401E	33015C0401F
LOMR-F	06-01-B697A	08/08/2006	THATCHER CONDOS, UNITS 1-7 -- 131 COURT STREET (NH)	33015C0402E 33015C0404E	33015C0402F 33015C0404F
LOMA	08-01-0536A	03/13/2008	LOT 113, RIVER BEND SUBDIVISION -- 28 RIVERBEND CIRCLE	33015C0404E	33015C0404F
LOMA	10-01-1244A	06/03/2010	LOT 3 #80 EPPING ROAD	33015C0401E	33015C0401F
LOMA	13-01-2073A	07/02/2013	8 MILLSTREAM DRIVE	33015C0401E	33015C0401F
LOMR-F	14-01-0030A	10/22/2013	LOT 31 -- 21 PATRICIA AVENUE	33015C0404E	33015C0404F
LOMA	14-01-0298A	11/12/2013	LOT 20 -- 7 MILLSTREAM DRIVE	33015C0401E	33015C0401F

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: EXETER, TOWN OF Community No: 330130

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		